

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2021

Submitted Date:

04/01/2021

Document Number:

700702512

## FIELD INSPECTION FORM

 Loc ID 322425 Inspector Name: Ramsey, Scott On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 96850  
 Name of Operator: TEP ROCKY MOUNTAIN LLC  
 Address: PO BOX 370  
 City: PARACHUTE State: CO Zip: 81635
**Findings:**

- 8 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name | Phone        | Email                              | Comment |
|--------------|--------------|------------------------------------|---------|
| , TEP        | 970-285-9377 | COGCCInspectionReports@terraep.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name    | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------|-------------|
| 210472      | WELL | PR     | 11/26/1980  | GW         | 045-06228 | VASSAR-HEATH 130 | PR          |

**General Comment:****OGCC Inspection Report Summary**

On Thursday 4/1/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Vasser-heath 130, at Location # 322425 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad. Location was bladed.

During this inspection the following possible compliance issues were observed:

1. Cellar next to meter house is open for wildlife to enter  
Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

| Location   |  |        |                 |
|--|--|--------|-----------------|
| <b>Lease Road:</b>                                     |  |        |                 |
| Type   | Access   |        |                 |
| comment:   |  |        |                 |
| Corrective ActionL                                     |  | Date:  |                 |
| Overall Good: <input type="checkbox"/>                 |  |        |                 |
| <b>Signs/Marker:</b>                                   |  |        |                 |
| Type   | WELLHEAD   |        |                 |
| Comment:   |  |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type   | OTHER  |        |                 |
| Comment:   | meter houses   |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Emergency Contact Number:                              |  |        |                 |
| Comment:   | 911  |        |                 |
| Corrective Action:                                     |  |        | Date: _____     |
| <b>Good Housekeeping:</b>                              |  |        |                 |
| Type   | OTHER  |        |                 |
| Comment:   | Cellar next to meter house is open for wildlife to enter |        |                 |
| Corrective Action:                                     | Install means of egress or eliminate wildlife access.    | Date:  | 05/06/2021      |
| Overall Good: <input type="checkbox"/>                 |  |        |                 |
| <b>Spills:</b>   |  |        |                 |
| Type   | Area   | Volume |                 |
| In Containment: No                                     |  |        |                 |
| Comment:   |  |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                 |
| <b>Equipment:</b>                                      |  |        |                 |
| Type: Gas Meter Run                                    | # 2  |        | corrective date |
| Comment:   |  |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type: Other  | # 1  |        |                 |
| Comment:   | well head not on plunger lift                            |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type: Bradenhead                                       | # 1  |        |                 |
| Comment:   | Braden heads have a port for manual gauge monitoring     |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| <b>Venting:</b>  |  |        |                 |
| Yes/No   | NO   |        |                 |
| Comment:   |  |        |                 |

|                    |  |       |  |
|--------------------|--|-------|--|
| Corrective Action: |  | Date: |  |
|--------------------|--|-------|--|

**Flaring:**

|                    |  |       |  |
|--------------------|--|-------|--|
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

**Inspected Facilities**

Facility ID: 210472 Type: WELL API Number: 045-06228 Status: PR Insp. Status: PR

**Producing Well**

Comment: producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Culverts                |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
| Ditches          |                 |                         |                       |               |                          |         |
| Check Dams       |                 |                         |                       |               |                          |         |

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad. Location was bladed.

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402646740    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5392835">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5392835</a> |
| 700702517    | photo log            | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5392830">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5392830</a> |