

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/01/2021

Submitted Date:

04/01/2021

Document Number:

700702514

**FIELD INSPECTION FORM**Loc ID 335193 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

9 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260198	WELL	PR	06/11/2014	GW	045-07826	CLOUGH RMV 152-22	PR
260629	WELL	PR	03/23/2002	GW	045-07885	CLOUGH RMV 222-22	PR
281522	WELL	PR	03/21/2006	GW	045-11481	CLOUGH RWF 414-22	PR

**General Comment:****COGCC Inspection Report Summary**

On Thursday 4/1/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP RMV 152-22, at Location # 335193 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad. Location was bladed.

During this inspection the following possible compliance issues were observed:

1. Two (2) well head cellars do not provide egress for wildlife.
  2. One (1) dead man is not properly marked
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

## Location

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	OTHER		
Comment:	Two (2) well head cellars do not provide egress for wildlife.		
Corrective Action:	Install means of egress or eliminate wildlife access.	Date:	05/06/2021

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>				corrective date
Type: Horizontal Heated Separator	# 3			
Comment:				
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:	One (1) dead man is not properly marked			
Corrective Action:	Mark or remove dead man (anchor)			Date: 05/06/2021
Type: Plunger Lift	# 3			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 3			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 3			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 3			
Comment:	Braden heads have a port for manual gauge monitoring			
Corrective Action:				Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
-----------	----------	--

Inspector Name: Ramsey, Scott

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type			
Comment:			
Corrective Action:			Date:

**Inspected Facilities**Facility ID: 260198 Type: WELL API Number: 045-07826 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 260629 Type: WELL API Number: 045-07885 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

Facility ID: 281522 Type: WELL API Number: 045-11481 Status: PR Insp. Status: PR**Producing Well**Comment: producing

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams						
Ditches						
Rip Rap						
Sediment Traps						
Berms						
		Ditches				
Retention Ponds						
		Culverts				
Waddles						

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for tracking pad. Location was bladed.

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402646742	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5392837">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5392837</a>
700702519	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5392832">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5392832</a>