

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/02/2021

Submitted Date:

04/02/2021

Document Number:

696303105

FIELD INSPECTION FORMLoc ID 454976 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neighbors, Cory		cneighbors@hpres.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455068	WELL	PR	05/02/2019	OW	123-46837	RSU Anschutz Fed 4-62-11-1724C	PR
455074	WELL	PR	08/05/2019	OW	123-46843	RSU Anschutz Fed 4-62-11-3340C	PR
455076	WELL	PR	05/04/2019	OW	123-46844	RSU Anschutz Fed 4-62-11-4956C	PR
455083	WELL	PR	05/05/2019	OW	123-46850	RSU Anschutz Fed 4-62-11-4841CN	PR
455085	WELL	PR	05/07/2019	OW	123-46852	RSU Anschutz Fed 4-62-11-4841CS	PR
455089	WELL	PR	05/06/2019	OW	123-46856	RSU Anschutz Fed 4-62-11-3225C	PR
455091	WELL	PR	05/05/2019	OW	123-46858	RSU Anschutz Fed 4-62-11-6457C	PR

General Comment:

Follow-Up Inspection to FIR 696301756 dated 04.27.2020

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Vault at Tank berm missing Capacity, see photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/07/2021
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical Containers at Wellheads - Labels are fading on Tanks 1, 2, & 3. See photos		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/07/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Risers at VRUs are now marked		
Corrective Action:		Date:	

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	

Equipment:			corrective date
Type: LACT	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: VRU	# 3	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 7	
Comment:	Appear to be plumbed to surface	
Corrective Action:		Date:
Type: Emission Control Device	# 3	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 16	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 7	
Comment:		
Corrective Action:		Date:
Type: Other	# 1	
Comment:	Line Heater	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with Crude Oil Tanks				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	10	400 BBLs	STEEL AST		40.323220,-104.301720
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	455068	Type:	WELL	API Number:	123-46837	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	455074	Type:	WELL	API Number:	123-46843	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	455076	Type:	WELL	API Number:	123-46844	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	455083	Type:	WELL	API Number:	123-46850	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	455085	Type:	WELL	API Number:	123-46852	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	455089	Type:	WELL	API Number:	123-46856	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			
Facility ID:	455091	Type:	WELL	API Number:	123-46858	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	PR								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
Routine Field Inspection. Risers at VRUs have been marked. Chemical Tanks at Wellheads Labels are fading on Tanks 1, 2, & 3. Vault at Tank berm missing Capacity Labels.	petrie	04/02/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402647679	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5393638
696303106	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5393630