

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK-66S95W /36SWSE

Location ID: 335029



Photo #3412 from entrance to location.



Photo #3413 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK-66S95W /36SWSE

Location ID: 335029



Photo #2821 from inspection #699802549 conducted on 2/5/21.

Photo #3416 Location lacks stabilization.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK-66S95W /36SWSE

Location ID: 335029



Photo #2822 from inspection #699802549 conducted on 2/5/21.



Photo #3417 No form of tracking control at entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK-66S95W /36SWSE

Location ID: 335029



Photo #3420 Storm water is being obstructed.



Photo #2824 from inspection #699802549 conducted on 2/5/21.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK-66S95W /36SWSE

Location ID: 335029



Photo #3421 Storm water is being obstructed.

Photo #2825 from inspection #699802549 conducted on 2/5/21.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC DIAMOND ELK-66S95W /36SWSE

Location ID: 335029



Photo #3418 Rill erosion occurring in ditch.



Photo #3419 No velocity checks located in ditch.