

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION Receive Date: 11/05/2020 Document Number: 402523738

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and

Operator Information

OGCC Operator Number: 10459 Contact Person: Nathan Bennett Company Name: EXTRACTION OIL & GAS INC Phone: (720) 354-4616 Address: 370 17TH STREET SUITE 5300 Email: nbennett@extractionog.com City: DENVER State: CO Zip: 80202 Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes [X] No []

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 321352 Location Type: Production Facilities Name: ALMQUIST-62N69W Number: 34NESE County: BOULDER Qtr: NESE Section: 34 Township: 2N Range: 69W Meridian: 6 Latitude: 40.091470 Longitude: -105.096960

Description of Corrosion Protection

Extraction's corrosion procedures are detailed in its Flowline Management SOP. Coating materials will be used that minimize internal and external corrosion, such as internally coated pipe or stainless steel for water service, and externally coated FBE on all buried steel pipe. If flowlines are repaired due to corrosion, Extraction will investigate the failure, promptly respond with the appropriate remedial actions and determine the root cause and apply corrective actions as necessary. Extraction retains records of its chemical program in the form of Failure Analysis Reports, records of chemical invoices and chemical delivery.

Description of Integrity Management Program

Extraction's integrity management program is detailed in its Flowline Management SOP, which covers flowline installation, operation, maintenance, inspection, testing, and repairs. Prior to beginning any project involving flowlines, Extraction ensures the project plans, flowline installation, flowline maintenance (including repairs) and all flowline inspection and testing projects meet the requirements of the Flowline Management SOP. All pressure tests on flowlines will be conducted by an independent, third party qualified to do such testing. Precautions shall be taken to protect employees and the general public.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 462641 Flowline Type: Wellhead Line Action Type: Out of Service

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 321435 Location Type: Well Site
Name: ALMQUIST MB-62N69W Number: 34NWSE
County: BOULDER No Location ID
Qtr Qtr: NWSE Section: 34 Township: 2N Range: 69W Meridian: 6
Latitude: 40.093366 Longitude: -105.099679

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 02/20/2005
Maximum Anticipated Operating Pressure (PSI): 398 Testing PSI: 398
Test Date: 03/29/2018

OFF LOCATION FLOWLINE Out of Service

Date: 10/12/2020

Entire Line Removal

Partial Line Removal

Description of Out of Service:

Flowline/Riser is locked out and tagged out.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 462643 Flowline Type: Wellhead Line Action Type: Abandonment Verification

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 321352 Location Type: Well Site
Name: ALMQUIST-62N69W Number: 34NESE
County: BOULDER No Location ID
Qtr Qtr: NESE Section: 34 Township: 2N Range: 69W Meridian: 6
Latitude: 40.091470 Longitude: -105.096960

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 10/28/1991
Maximum Anticipated Operating Pressure (PSI): 500 Testing PSI: 540
Test Date: 03/23/2018

OFF LOCATION FLOWLINE Abandonment Verification

Date: 10/25/2019

Abandonment Verification

The abandoned Off-Location Flowline was located within the jurisdiction(s) of the following local government(s).
(No Jurisdiction)

Description of Abandonment Verification:

The entire 2' steel line was removed from the ground. No 1' poly line existed.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 462642 Flowline Type: Wellhead Line Action Type: Out of Service

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 321438 Location Type: Well Site
Name: ALMQUIST MB-62N69W Number: 34SESE
County: BOULDER No Location ID
Qtr Qtr: SESE Section: 34 Township: 2N Range: 69W Meridian: 6
Latitude: 40.088530 Longitude: -105.095380

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375
Bedding Material: Native Materials Date Construction Completed: 08/30/1993
Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Out of Service

Date: 10/12/2020

Entire Line Removal Partial Line Removal

Description of Out of Service:

Flowline/Riser is locked out and tagged out.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 462644 Flowline Type: Wellhead Line Action Type: Out of Service

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 321436 Location Type: Well Site
Name: ALMQUIST-62N69W Number: 34SWSE
County: BOULDER No Location ID
Qtr Qtr: SWSE Section: 34 Township: 2N Range: 69W Meridian: 6
40.089240 -105.099800

Latitude:

Longitude:

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.375

Bedding Material: Native Materials Date Construction Completed: 10/06/1993

Maximum Anticipated Operating Pressure (PSI): 498 Testing PSI: 498

Test Date: 03/23/2018

OFF LOCATION FLOWLINE Out of Service

Date: 10/12/2020

Entire Line Removal

Partial Line Removal

Description of Out of Service:

Flowline/Riser is locked out and tagged out.

OPERATOR COMMENTS AND SUBMITTAL

Comments This form is being submitted as a December 1, 2020 update to include a gis shapefile and description of the integrity management plan and corrosion protection plan for these flowlines.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: Date: 11/05/2020 Email: emartinez@h2eincorporated.com

Print Name: Emily Martinez Title: Environmental Scientist

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved: Director of COGCC Date:

Conditions of Approval

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

402523741	OFF-LOCATION FLOWLINE GEODATABASE SHP
402523742	OFF-LOCATION FLOWLINE GEODATABASE SHP
402523743	OFF-LOCATION FLOWLINE GEODATABASE SHP
402525013	OFF-LOCATION FLOWLINE GEODATABASE SHP

Total Attach: 4 Files

General Comments

User Group

Comment

Comment Date

		Stamp Upon Approval
--	--	---------------------

Total: 0 comment(s)

