

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/09/2021

Submitted Date:

04/11/2021

Document Number:

701500276

FIELD INSPECTION FORM

Loc ID 335884	Inspector Name: Moran, Rick	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED
Operator Information: OGCC Operator Number: 100264 Name of Operator: XTO ENERGY INC Address: 110 W 7TH STREET City: FORT WORTH State: TX Zip: 76102				Findings: 21 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested
				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Clark, Erin	405-319-3250	erin.k.clark@exxonmobile.com	Lead regulatory coordinator
Dooling, Jes	832-624-0810	jessica.dooling@exxonmobile.com	Lead regulatory coordinator
Sutton, Derek		derek_sutton@xtoenergy.com	Area foreman
Thompson, Bud		BLThomps@BLM.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
285712	WELL	PR	06/08/2012	GW	103-10818	PICEANCE CREEK UNIT 296-7A5	PR
285713	WELL	PR	01/01/2020	GW	103-10819	PICEANCE CREEK UNIT 296-7A4	PR
285714	WELL	SI	01/01/2021	GW	103-10820	PICEANCE CREEK UNIT 296-7A3	SI
285715	WELL	SI	06/01/2020	GW	103-10821	PICEANCE CREEK UNIT 296-7A2	SI
285716	WELL	SI	12/01/2020	GW	103-10822	PICEANCE CREEK UNIT 296-7A1	SI
285717	WELL	PR	01/01/2021	GW	103-10823	PICEANCE CREEK UNIT 296-7A9	PR
285718	WELL	PR	06/01/2019	GW	103-10824	PICEANCE CREEK UNIT 296-7A8	PR
285719	WELL	PR	01/17/2009	GW	103-10825	PICEANCE CREEK UNIT 296-7A7	PR
285720	WELL	PR	12/01/2020	GW	103-10826	PICEANCE CREEK UNIT 296-7A6	PR

General Comment:

A routine inspection identified the following compliance issues:

- 1) Compaction incomplete on location. Photos 8 & 9. Complete by 6-12-2021.

Location is within a CDPHE Reg 42 Limited use & quality area, Rule 1202.d Mule deer severe winter range area, Rule 1202.d Mule deer winter concentration area, Rule 309.e.1 Greater sage grouse general habitat management area, and a Black bear area.

This is a summary of inspection report 701500276.

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign at location entrance.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Chemical.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Ancillary equipment	# 5		
Comment:	Chemical containers.		
Corrective Action:		Date:	
Type: Other	# 4		
Comment:	Well manifold, compressor on skid, trailers.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		

Comment: Telemetry.		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 9		
Comment: Bradenhead access present.		Date:	
Corrective Action:		Date:	
Type: Plunger Lift	# 9		
Comment:		Date:	
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		Date:
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 285712	Type: WELL	API Number: 103-10818	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 285713	Type: WELL	API Number: 103-10819	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 285714	Type: WELL	API Number: 103-10820	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Last recorded production 12-2020.				
Corrective Action:			Date:	
Facility ID: 285715	Type: WELL	API Number: 103-10821	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Last recorded production 5-2020.				
Corrective Action:			Date:	
Facility ID: 285716	Type: WELL	API Number: 103-10822	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment: Last recorded production 11-2020.				
Corrective Action:			Date:	
Facility ID: 285717	Type: WELL	API Number: 103-10823	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 285718	Type: WELL	API Number: 103-10824	Status: PR	Insp. Status: PR
Producing Well				
Comment: PR				
Corrective Action:			Date:	
Facility ID: 285719	Type: WELL	API Number: 103-10825	Status: PR	Insp. Status: PR

Producing Well			
Comment:	PR		
Corrective Action:		Date:	
Facility ID:	285720	Type:	WELL
API Number:	103-10826	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	PR		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Culverts						
Compaction	Fail					
Retention Ponds						
Waddles				Material Handling And Spill Prevention		
Gravel		Gravel				

Comment: [Cattle guard across location entrance. Tracking on location near wells.](#)

Corrective Action: [Install, maintain, or provide documentation of post construction management plan or BMP's.](#)

Date: 06/12/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	284684	200090057	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500277	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5400386