

Location

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Asequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action: Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Cattle		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Cattle		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		

Comment:	Appears to be plumbed to surface.			Date:	
Corrective Action:				Date:	
Type: Plunger Lift	# 1				
Comment:				Date:	
Corrective Action:				Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:	Shares containment with crude oil tank				
Corrective Action:					Date:

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					
Date:					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
Date:				

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			
Date:			

Flaring:

Type			
------	--	--	--

Comment:		
Corrective Action:		Date:

--	--	--

Inspected FacilitiesFacility ID: 244380 Type: WELL API Number: 123-12174 Status: SI Insp. Status: SI**Idle Well**Purpose: Shut In Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary On (4/13/21) at approximately (10:25 HRS), I, Inspector (Abe Serna), Conducted an on-site inspection at (UPRR 36 PAN AM C1) (Noble Energy), at (Location #311342) in (Weld County) Colorado. While there, I observed a (SI Well) During this inspection no compliance issues were observed. No follow up on this site inspection needs to be conducted. This is a summary of inspection report.</p>	sernaa	04/13/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698702940	Photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5401794