

# Inspection Photos

API: 071-06815

Operator: WAPITI OPERATING LLC

Inspection Date: 4/12/2021



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

API: 071-06815 | Date: 4/12/2021

## Inspection Photos



**Photo 1.** Facing north toward the access road. It appears grading was recently performed however, there is signs of vehicle rutting. The road is not stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06815 | Date: 4/12/2021

## Inspection Photos



**Photo 2.** Facing north along the access road. The road is not stabilized



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06815 | Date: 4/12/2021

## Inspection Photos



**Photo 3.** A ditch was bladed to divert stormwater off the road however, BMP's are required to prevent sediment discharge. BMP's such as a sediment trap, rip/rap, check dams need to be installed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06815 | Date: 4/12/2021

## Inspection Photos



**Photo 4.** Facing toward the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06815 | Date: 4/12/2021

## Inspection Photos



**Photo 5.** There is produced water leaking from the wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06815 | Date: 4/12/2021