

Inspection Photos

API: 071-06816

Operator: WAPITI OPERATING LLC

Inspection Date: 4/12/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-06816 | Date: 4/12/2021

Inspection Photos



Photo 1. Facing northeast along the access road. The road was recently graded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06816 | Date: 4/12/2021

Inspection Photos



Photo 2. A ditch was bladed to divert stormwater off the road however, BMP's are required to prevent sediment discharge. BMP's such as a sediment trap, rip/rap, check damns need to be installed. Photo on the right shows sediment accumulation from the access road. Erosion controls are required to stabilize the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06816 | Date: 4/12/2021

Inspection Photos



Photo 3. The road which was recently bladed has pushed loose material off the road. There is insufficient stabilization along the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06816 | Date: 4/12/2021

Inspection Photos



Photo 4. There is sediment accumulation near the culvert which needs to be maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06816 | Date: 4/12/2021

Inspection Photos



Photo 5. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06816 | Date: 4/12/2021

Inspection Photos



Photo 6. There is slight produced water leaking from the wellhead.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-06816 | Date: 4/12/2021