

Inspection Photos
Operator: Hilcorp Energy
Facility: 067-07403
Date: 4/12/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing, partially returned to alfalfa crop field in the eastern project area, and revegetated with upland grasses such as sand dropseed, western wheatgrass, crested wheatgrass, and smooth brome in the non-irrigated portions.



Photo 3. View of the western project area facing southward.



Photo 4. View of kochia debris within the southern project area, needs to be removed and properly disposed of.



Photo 5. View of the reference area comprised of irrigated alfalfa field. Portions of the project area are returned to alfalfa production. Other portions are not irrigated and comprised of upland grasses.