

Inspection Photos
Operator: IKAV
Facility: 067-07455
Date: 4/12/2021



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the northern project area from the northeastern corner facing westward. Revegetation is progressing with smooth brome and sand dropseed.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of the dense kochia debris within the southeastern project area, needs to be removed and properly disposed of.



Photo 5. View of the reference area comprised of crop field, largely fallow at this time, with grasses such as western wheatgrass, and smooth brome.