

Inspection Photos  
Operator: Hilcorp Energy  
Facility: 067-08319  
Date: 4/12/2021



Photo 1. View of the project area from the well pad entrance facing center. Equipment observed during previous inspection, is no longer present.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is conducted within the interim reclamation areas. Germination observed. However, bare soils are not protected and erosion controls not installed.





Photo 3. View of the western project area from the northwestern corner facing southward.