

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/13/2021

Submitted Date:

04/14/2021

Document Number:

690102378

FIELD INSPECTION FORM
 Loc ID 319720 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10110

Name of Operator: GREAT WESTERN OPERATING COMPANY LLC

Address: 1001 17TH STREET #2000

City: DENVER State: CO Zip: 80202

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
		cogccinspections@gwogco.com	
Chesson, Robert		robert.chesson@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
201100	WELL	SI	03/03/2021	GW	001-06503	DAVIS 1-30	EG

General Comment:

COGCC Engineering Integrity Inspection; Flowline Removal Confirmation

Inspected FacilitiesFacility ID: 201100 Type: WELL API Number: 001-06503 Status: SI Insp. Status: EG**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:
 Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Davis 1-30) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #402634865 received on 03/22/2021. COGCC form 42 notice of flowline pre-abandonment notice Doc #402601856 dated 04/07/2021. On and off location flowlines (wellhead, dump and process) have been removed (confirmed via communications and inspection); No flowline risers were observed at the (PA) wellhead or facility areas during this field inspection. Open excavations were observed in the area of the produced water tank (equipment and tanks removed). Excavation and remediation activities in response to the historical release is in progress.

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #402652706 received on 04/08/2021: Potential impacts to soil were observed beneath the partially buried produced water tank during facility closure activities on April 8, 2021, at approximately 9:00 am. The release is completely contained on-site, neither surface water nor groundwater were impacted, no injuries occurred as a result of the release, and cleanup is ongoing. No flowlines were observed in the open excavation in the area of the produced water tank.	maclarej	04/14/2021