

Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Albert Martinez #1 well head and pump jack.



Drive belts on pump jack have broken. EPS staff shut down power to electric motor.

Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Drop out tank for domestic tap.



Electrical supply to pump jack turned off during this inspection.

Inspection Photos
Location Name: Albert Martinez #1
API: 05-007-06253



Albert Martinez #1 tank battery. Anchors were observed during this inspection. Tanks are not attached to anchors.



Albert Martinez #1 and Nielson #4 ASTs.