

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Chavez #1 well head and pump jack with oil impacted soil and vegetation.



Chavez #1 well head is wet and stained. Surrounding area is wet and stained with oil.

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



Oil puddle around well head and stained/wet vegetation and soil.



Trailer stored on location.

Inspection Photos
Location Name: Chavez #1
API: 05-007-06120



300 bbl. crude oil AST for Chavez #1 and #2.



Tank battery sign is not compliant with Rule 605.e(2).