

Inspection Photos
Location Name: Chavez #2
API: 05-067-06136



Chavez #2 pump jack and well head.



Electric motor is not present.

Inspection Photos
Location Name: Chavez #2
API: 05-067-06136



View of AST used by Chavez #1 and #2 wells.



Soil from the Albert Martinez #1 REM #13940 has been removed.