

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2021

Submitted Date:

04/14/2021

Document Number:

688800889

**FIELD INSPECTION FORM**Loc ID 320860 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 900

Name of Operator: ALAMOSA DRILLING INC

Address: 8150 N. CENTRAL EXPY - STE 750

City: DALLAS State: TX Zip: 75205-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

8 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Leonard, Mike		mike.leonard@state.co.us	
Heil, John		john.heil@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205258	WELL	PR	06/01/2020	OW	007-06136	CHAVEZ 2	EI

**General Comment:**

On April 9, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Chavez #2. For the most recent field inspection report of this facility, please refer to document #688800794.

Location					
<b>Lease Road:</b>					
Type	Access				
comment:					
Corrective Action	L				Date:
Overall Good: <input checked="" type="checkbox"/>					
<b>Signs/Marker:</b>					
Type	BATTERY				
Comment:	Tank battery sign is not compliant with Rule 605.e(2).				
Corrective Action:	Install sign to comply with Rule 605.e(2).				Date: 05/14/2021
Type	WELLHEAD				
Comment:	Sign mounted to fencing around pump jack and well head. Well head sign is not compliant with Rule 605.d(1).				
Corrective Action:	Install sign to comply with Rule 605.d(1).				Date: 05/14/2021
<b>Emergency Contact Number:</b>					
Comment:	Emergency services contact information is not posted on location signs.				
Corrective Action:	Install sign to comply with Rule 605.e(2).				Date: 04/29/2021
Overall Good: <input type="checkbox"/>					
<b>Spills:</b>					
Type	Area	Volume			
In Containment: No					
Comment:					
<input type="checkbox"/> Multiple Spills and Releases?					
<b>Fencing/:</b>					
Type	PUMP JACK				
Comment:	Post and wire fencing around pump jack and well head.				
Corrective Action:					Date:
<b>Equipment:</b>					
					corrective date
Type: Flow Line	# 1				
Comment:					
Corrective Action:					Date:
Type: Pump Jack	# 1				
Comment:					
Corrective Action:					Date:
Type: Prime Mover	# 0				
Comment:					
Corrective Action:					Date:
<b>Tanks and Berms:</b>					
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		37.018064,-106.875094

Comment:	Shared tank battery with Chavez #1.	
Corrective Action:		Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
007-06136
007-06120

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:



**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On April 9, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Chavez #2. For the most recent field inspection report of this facility, please refer to document #688800794. Well head sign is not compliant with Rule 605.d(1). Install sign to comply with Rule 605.d(1) within 30 days. Tank battery sign is not compliant with Rule 605.e(2). Install sign to comply with Rule 605.e (2). Emergency services contact information is not posted on location signs.	hughesjo	04/14/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800890	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403628">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403628</a>