



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PUMP JACK

Comment: [fabricated angle iron](#)

Corrective Action:

Date:

Type OTHER

Comment: [ancillary equipment has fabricated round stock and steel pole](#)

Corrective Action:

Date:

**Equipment:**

corrective date

Type: Ancillary equipment

# 1

Comment: [electric panel, meter box and transformers](#)

Corrective Action:

Date:

Type: Bradenhead

# 1

Comment: [appears to be plumbed to surface](#)

Corrective Action:

Date:

Type: Prime Mover

# 1

Comment: [electric motor](#)

Corrective Action:

Date:

Type: Pump Jack

#

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 239944 Type: WELL API Number: 123-07732 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:  Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 09/28/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:  Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p><a href="#">COGCC Inspection Report Summary</a>                      On 4-14-2021 at approximately 1400hrs , I, Robbie Revas conducted an inspection of KPK well                      Yoxall Farms #1 API # 05-123-07732 in Weld County Colorado.                      The purpose of this inspection was to confirm compliance with the COGCC Director's order under rule 901.a. of the Rules and Regulations of the Colorado Oil and Gas Conservation Commission, 2 CCR 404-1 ("Rule" or "Rules"). As part of this order the operator KPK (Operator No. 46290) was ordered to immediately suspend all production operations at these assigned location.                      I inspected this location and confirmed operations appeared to be suspended as equipment on site does appear to be shut off and valves appear to be closed. See attached photos in attachments of this inspection.                      On 4-14-2021 the operator KPK notified COGCC staff Jeremy Ferrin through email that all 87 locations listed in the order had suspended all production operations at these locations. All corrective action from previous and further inspection must be completed to comply with COGCC rules.</p> <p style="text-align: center;">This is a summary of inspection report.</p>	revasr	04/14/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303676	location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403706">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403706</a>