

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/08/2021

Submitted Date:

04/08/2021

Document Number:

699103360**FIELD INSPECTION FORM**Loc ID 428267 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		EHSRC@bonanzacrk.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
447084	TANK BATTERY	AC	07/29/2016		-	North Platte 24-34 Pad	AC

**General Comment:**

This is a follow up to FIRR #402648808. The CA's did not meet expectations.  
This is a inspection on just the Archrock Compressors.

**Location**Overall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type

OTHER

Comment:

Oily waste on Compressor skids needs to be removed for good housekeeping. See attached photos.

Corrective Action:

Comply with Rule 606.

Date: 04/02/2021

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Compressor

# 2

Comment:

Appear to have multiple leaking valves/ fittings on both compressors causing oily waste on skid. See attached photo.

Corrective Action:

Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 04/02/2021

**Venting:**

Yes/No

NO

Comment:

Corrective Action:

Date:

**Flaring:**

Type

Comment:

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 447084 Type: TANK API Number: - Status: AC Insp. Status: AC

**Producing Well**

Comment: AC

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 4/8/21 at approximately 0801hrs, I, Inspector Adam Burns, Conducted an on-site inspection to FIRR document #402648808 at North Platte 24-34 Compressor's Location of Bonanza Creek Energy, at Facility ID # 447084 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Appear to have multiple leaking valves/ fittings on both compressors causing oily waste on skid. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 4/2/21.</p> <p>Oil waste on the compressors, needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 4/2/21</p> <p>See attached photos.</p> <p>This is a summary of inspection report.</p>	burnsa	04/08/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402652775	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5398048">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5398048</a>
699103361	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5398046">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5398046</a>