

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/13/2021

Submitted Date:

04/15/2021

Document Number:

700600261

FIELD INSPECTION FORM

Loc ID 307436 Inspector Name: Kosola, Jason On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10705
Name of Operator: EVERGREEN NATURAL RESOURCES LLC
Address: 1875 LAWRENCE ST STE 1150
City: DENVER State: CO Zip: 80202

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Inspections, Evergreen		cogcc.evergreen@enrllc.com	All Inspections
Costa, Ryan		ryan.costa@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
217662	WELL	PR	10/01/2002	GW	071-06441	ALBERT 13-15	EI

General Comment:

This is an environmental inspection to follow up on COGCC Inspection 690201393 which found what appears to be an oily substance in the produced water pit.

Environmental inspection found that oily substance that appears in pit is likely shale outcrop that has been saturated with stormwater. Pit contents did not have a hydrocarbon sheen or odor. RKI GX-6000 photoionization detector did not detect the presence of volatile organic compounds (VOCs) within produced water pit. Due to the lack of odor and no VOC detect is it likely that pit contents are the same shale that outcrops just west of well pad (see attached photos). Additionally the Colorado 34-16 (071-06358) located nearby at a similar elevation and stratigraphic interval also has the same pit contents and also is found just below a prominent sandstone layer. Analytical results from sampling of the pit contents in August 2018 did not find the presence of hydrocarbons in the Colorado 34-16 pit contents. See inspection 700600262. Due to these facts the corrective action to investigate oily pit contents from inspection 690201393 has been removed.

This inspection is being entered to document the investigation into the pit contents and document the shale outcrop found adjacent to the well pad. All other corrective actions from previous inspections remain in effect.

Inspected Facilities

Facility ID: 217662 Type: WELL API Number: 071-06441 Status: PR Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700600263	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5404353