

Inspection Photos
Operator: Linde Operating
Facility: 083-06256
Date: 4/12/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the project area from the northwestern corner facing center. Netting scaffold appears to have collapsed. Netting in disrepair.



Photo 3. Another view of pit area. Liner may be compromised. Netting in disrepair.



Photo 4. View of the western project area facing northward. Area around dry hole marker is in use for parking and vehicle traffic. This area will require reclamation after plugging.



Photo 5. View of the reference area comprised of pinyon and juniper woodland with understory of serviceberry, cliffrose, and Indian ricegrass.