

Inspection Photos
Operator: Linde Inc.
Facility: 083-06522
Date: 4/6/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is progressing with a variety of grasses such as Indian ricegrass, crested wheatgrass, and James galleta.



Photo 3. View of the northern project area from the northwestern corner facing eastward.



Photo 4. View of tamarisk growing in the northern project area, needs to be removed.



Photo 5. View of erosional channel in the northern project area needs stabilization.



Photo 6. View of Russian knapweed within the northeastern interim reclamation area. Approximately 200 individuals observed.



Photo 7. View of the reference area comprised of pinyon and juniper woodland with understory of serviceberry, cliffrose, and Indian ricegrass.