

Inspection Photos  
Operator: Linde  
Facility: 083-06536  
Date: 4/6/2021



Photo 1. View of the eastern project area from the well pad entrance. Two soil piles observed on well pad are covered in decomposing plastic.





Photo 2. View of trench, approximately 2.5 feet deep and 3 feet wide, and silt fence in the eastern project area.





Photo 3. View of silt fence in the southeastern project area, in disrepair.





Photo 4. Another view of trench and silt fence in the eastern project area. Russian thistle and plastic debris observed in trench.





Photo 5. View of decomposing plastic covering soil pile in the eastern project area.





Photo 6. View of revegetation with Indian ricegrass and rubber rabbitbrush within the eastern project area, facing northward.





Photo 7. View of plastic debris blown off of the well pad.





Photo 8. View of excavated area in the northern project area and trench in foreground





Photo 9. View of covered soil pile in the western project area.





Photo 10. View of surface flowlines need to be properly abandoned.





Photo 11. View of access road that needs to be reclaimed.





Photo 12. View of flowline at drainage intersection. Valve is open into drainage.





Photo 13. View of the reference area comprised of pinyon and juniper woodland with understory of serviceberry, cliffrose, and Indian ricegrass.