

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/15/2021

Submitted Date:

04/16/2021

Document Number:

701500356

**FIELD INSPECTION FORM**

Loc ID 314685 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74740  
Name of Operator: RIO MESA RESOURCES INC  
Address: P.O. BOX 984  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 5 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Hayes, Mike	970-620-2257	hayespetroleum@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229261	WELL	SI	07/01/2020	OW	103-06356	HILL, CARRIE & DON 5	SI

**General Comment:**

A routine inspection identified the following compliance issues:  
 1) Stormwater channels on location & choking vegetation. Photos 4 & 5. Complete by 6-16-2021.  
 Location is within a Rule 1202.c Aquatic sportfish management area, Rule 1202.d Mule deer severe winter range area, and Rule 1202.d Mule deer winter concentration area.  
 This is a summary of inspection report 701500356.

**Location**

Overall Good:

**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

**Emergency Contact Number:**

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type				corrective date
Pump Jack	# 1			
Comment:				
Corrective Action:		Date:		
Deadman # & Marked	# 4			
Comment:				
Corrective Action:		Date:		
Bradenhead	# 1			
Comment:	Bradenhead access present.			
Corrective Action:		Date:		

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition Adequate

Other (Content)

Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	

**Venting:**

Yes/No	NO				
Comment:					
Corrective Action:				Date:	

**Flaring:**

Type					
Comment:					
Corrective Action:				Date:	

**Inspected Facilities**

Facility ID: 229261 Type: WELL API Number: 103-06356 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction						

Comment: [Stormwater channels on edge of location choking out vegetation off location.](#)

Corrective Action: **Install, maintain, or provide documentation of post construction management plan or BMP's.**

Date: 06/16/2021

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500357	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5405676">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5405676</a>