

Inspection Photos
Location Name: Duncan Van Schaick Unit 1 2
Location ID: 313051



Photo 1. Overview of location taken facing northwest. Dried annual weeds on location.



Photo 2. No bradenhead access apparent. Dried annual weeds on location.

Inspection Photos
Location Name: Duncan Van Schaick Unit 1 2
Location ID: 313051



Photo 3. Tank label incomplete and faded.




Photo 4. Tank overflow. Dried annual weeds.