

Inspection Photos
Operator: Hilcorp
Facility: 067-09460
Date: 4/15/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Dense weed debris observed on the well pad edges.



Photo 3. View of dense weed debris within the northeastern portion of the project area.



Photo 4. View of erosional rilling at the well pad entrance, facing downslope.



Photo 5. View of the reference area comprised of pinyon and juniper woodland with understory of cholla, sagebrush, western wheatgrass, and Indian ricegrass. Inset shows portion of reference area comprised of cultivated wheat field in early vegetative condition.