

**Inspection Photos**  
**Operator: Hilcorp**  
**Facility: 067-09461**  
**Date: 4/15/2021**



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western project area from the southwestern corner facing northward. Vegetation within the outer project area is in cultivation. Vegetation on the edges of the project area is comprised of grasses such as crested wheatgrass.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of the reference area comprised of grass crop field in early vegetative condition.