

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/16/2021

Submitted Date:

04/19/2021

Document Number:

701500372**FIELD INSPECTION FORM**Loc ID 315373 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10654Name of Operator: LASSO OIL & GAS LLCAddress: 3021 RIDGE RD #156City: ROCKWALL State: TX Zip: 75032**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Boulger, Levin		lboulger@31operating.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230730	WELL	PR	11/08/2000	GW	103-08399	CONTINENTAL 2-21	PR

**General Comment:**

A follow up inspection of documents:

- 1) FIR 700404692 dated 12-22-2020.

The following compliance issues were resolved:

- 1) The emergency phone number is answered.

The following compliance issues are uncompleted:

- 1) Report past due monthly operations on Form 7.
- 2) Provide bradenhead access. Photo 2. Complete by 2-1-2021.
- 3) Calibrate gas meter. Photo 7. Complete by 2-1-2021.

Additional compliance issues:

- 1) Stormwater channels run on & off location. Photos 1, 4, 5, 6. Complete by 6-19-2021.

Location is within a Rule 1202.c Aquatic sportfish management area, Rule 1202.d Mule deer migration corridor, Rule 1202.d Elk winter concentration area, and a Black bear area.

This is a summary of inspection report 701500372.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Bradenhead access is not present.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2).		Date: 02/01/2021
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 1		

Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Most recent meter calibration in June 2019.		
Corrective Action:	Calibrate gas metering equipment annually to comply with rule 430.d.(1).		Date: 02/01/2021
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<50 BBLs	PBV FIBERGLASS		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	40 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 230730 Type: WELL API Number: 103-08399 Status: PR Insp. Status: PR**Producing Well**Comment: [Last reported production in May 2020. Audible gas flow at well, meter building & separator. Report past due monthly operations.](#)[Submit required Form 7\(s\) to COGCC per rule 413.b.](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches						
Other						Native vegetaton on location.
Berms						

Comment: Stormwater channel that enters the location from the uphill side, runs through the location, and exits downhill on the road.

Corrective Action: Install, maintain, or provide documentation of post construction management plan or BMP's.

Date: 06/19/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500373	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5406923">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5406923</a>