

Inspection Photos
Location Name: Duncan Van Schaick 4
Location ID: 333337



Photo 1. Overview of location taken facing northwest. Dried annual weeds on location.



Inspection Photos
Location Name: Duncan Van Schaick 4
Location ID: 333337



Photo 2. No bradenhead access apparent. Dried annual weeds on location.



Photo 3. No bradenhead access apparent. Dried annual weeds on location.



Inspection Photos
Location Name: Duncan Van Schaick 4
Location ID: 333337



Photo 4. Tank labels faded/incomplete.



Photo 5. Erosion on access road.

Inspection Photos
Location Name: Duncan Van Schaick 4
Location ID: 333337



Photo 6. Erosion rill transporting sediment off access road.



Photo 7. Sediment leaving access road.

