

Inspection Photos
Location Name: Van Schaick C 10
Location ID: 313150



Photo 1. Overview of location taken facing northwest. Dried annual weeds on location.



Inspection Photos
Location Name: Van Schaick C 10
Location ID: 313510



Photo 2. No bradenhead access apparent. Dried annual weeds on location.



Photo 3. Tank labels faded/incomplete. Dried annual weeds on location.



Inspection Photos
Location Name: Van Schaick C 10
Location ID: 313510



Photo 4. Erosion rill on access road.



Photo 5. Sediment transport off access road.



Inspection Photos
Location Name: Van Schaick C 10
Location ID: 313510



Photo 6. Erosion rill on access road.



Photo 7. Sediment transport off access road.

