

## Inspection Photos

Location Name: CAERUS PICEANCE LLC WALLING-68S96W /1NWSE

Location ID: 334062



Photo #3543 from entrance to location.

Photo #3544 from entrance to location.

## Inspection Photos

Location Name: CAERUS PICEANCE LLC WALLING-68S96W /1NWSE

Location ID: 334062



**Photo #3548 Location lacks stabilization.**



**Photo #3549 Location lacks stabilization.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC WALLING-68S96W /1NWSE

Location ID: 334062



**Photo #3550 No form of tracking BMP at entrance to location.**



**Photo #3545 Sediment has been transported off location.**

## Inspection Photos

Location Name: CAERUS PICEANCE LLC WALLING-68S96W /1NWSE

Location ID: 334062



**Photo #3546 Sediment has been transported off location.**



**Photo #3547 Sediment is choking off vegetation**