

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/09/2021

Submitted Date:

04/14/2021

Document Number:

688800887

**FIELD INSPECTION FORM**Loc ID 320854 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 900

Name of Operator: ALAMOSA DRILLING INC

Address: 8150 N. CENTRAL EXPY - STE 750

City: DALLAS State: TX Zip: 75205-

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

12 Number of Comments

7 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Heil, John		john.heil@state.co.us	
Mercer, Lauren		Lauren.Mercer@coag.gov	
Labowskie, Steve		steve.labowskie@state.co.us	
Moore, Todd	(214) 368-6700/ (719)342-1445	kiowagas@sbcglobal.net	All Inspections
Leonard, Mike		mike.leonard@state.co.us	
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205242	WELL	PR	06/01/2020	OW	007-06120	CHAVEZ 1	EI
457801	SPILL OR RELEASE	AC	10/05/2018		-	Chavez 1	EI

**General Comment:**

On April 9, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Chavez #1. For the most recent field inspection report for this facility, please refer to document #688800792.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:	AST is labeled with NFPA placard, contents, and capacity.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Well head sign is mounted to hog wire fencing around well head and pump jack. Well head sign is not compliant with Rule 605.d(1).		
Corrective Action:	Install sign to comply with Rule 605.d(1).		Date: 05/14/2021
Type	BATTERY		
Comment:	Tank battery sign is not compliant with Rule 605.e(2).		
Corrective Action:	Install sign to comply with Rule 605.e(2).		Date: 05/14/2021
Emergency Contact Number:			
Comment:	Emergency services contact information is not posted on location signs.		
Corrective Action:	Install signs to comply with Rule 605.e(2).		Date: 05/14/2021
<b>Good Housekeeping:</b>			
Type	STORAGE OF SUPL		
Comment:	Trailer stored on location.		
Corrective Action:	Comply with Rule 606.a.		Date: 04/29/2021
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
Crude Oil	WELLHEAD	<= 1 bbl	
Comment:	Well head and surrounding area are wet and stained with oil. Puddle of oil at base of well head.		
Corrective Action:	Control and contain spills/releases and clean up per Rule 912.a.		Date: 04/15/2021
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	PUMP JACK		
Comment:	Post and wire fencing around well head and pump jack.		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Flow Line	# 1		corrective date
Comment:			

Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Supply shed.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		37.018081,-106.875100
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Wells Served By Facilities Above**

API Number
007-06120
007-06136

**AirsID**

API Number	AirsID
------------	--------

**Venting:**

Yes/No		
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	205242	Type:	WELL	API Number:	007-06120	Status:	PR	Insp. Status:	EI
Facility ID:	457801	Type:	SPILL OR	API Number:	-	Status:	AC	Insp. Status:	EI

**Environmental****Spills/Releases:**

Type of Spill: \_\_\_\_\_

Estimated Spill Volume: \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action:

The operator will submit a Supplemental Spill Report requesting closure of Spill/Release Point ID #457801 with work proceeding under REM #11969, by April 15, 2021.

Date: 04/15/2021

Reportable: YES

GPS: Lat \_\_\_\_\_

Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_

Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

Lat

Long

DWR Receipt Num: \_\_\_\_\_

Owner Name: \_\_\_\_\_

GPS : \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_

Comment: \_\_\_\_\_

**Spill/Remediation:**

Comment: REM #11969 has an active status in the COGIS database.

Corrective  
Action:

Per Rule 913.e(2), the operator will submit a Supplemental Form 27, with a detailed project summary and status, for all existing remediation projects approved prior to January 15, 2021 by April 15, 2021.

Date: 04/15/2021

Emission Control Burner (ECB): \_\_\_\_\_

Comment: \_\_\_\_\_

Pilot: \_\_\_\_\_

Wildlife Protection Devices (fired vessels): \_\_\_\_\_

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>On April 9, 2021 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Alamosa Drilling Chavez #1. For the most recent field inspection report for this facility, please refer to document #688800792.</p> <p>Well head sign is mounted to hog wire fencing around well head and pump jack. Well head sign is not compliant with Rule 605.d(1). Install sign to comply with Rule 605.d(1).</p> <p>Emergency services contact information is not posted on location signs. Install signs to comply with Rule 605.e(2).</p> <p>Tank battery sign is not compliant with Rule 605.e(2). Install sign to comply with Rule 605.e(2).</p> <p>Well head and surrounding area are wet and stained with oil. Puddle of oil at base of well head. Control and contain spills/releases and clean up per Rule 912.a.</p> <p>The operator will submit a Supplemental Spill Report requesting closure of Spill/Release Point ID #457801 with work proceeding under REM #11969, by April 15, 2021.</p> <p>Per Rule 913.e(2), the operator will submit a Supplemental Form 27, with a detailed project summary and status, for all existing remediation projects approved prior to January 15, 2021 by April 15, 2021.</p>	hughesjo	04/14/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402659023	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403610">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403610</a>
688800888	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403608">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5403608</a>