

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/13/2021

Submitted Date:

04/21/2021

Document Number:

696104498

**FIELD INSPECTION FORM**Loc ID 305536 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

11 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		cogccinspection@pdce.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278877	WELL	PR	05/01/2019	OW	123-23107	RUFF 22-3	PR

**General Comment:**

This is a WELL inspection.  
Well(s): 1: Producing | PR.  
Battery (West side): Inactive | Shut-down.  
Battery (East side): Active.

Centralized Battery serves 3 Location IDs  
(305433, 305536, 332454).  
(Well(s): 1: Shut-In | SI ; 2: Producing | PR).

Refer to Field Inspection Report doc. #696104494 and/or Location ID #305433  
for Battery / Facility, Equipment info.

### Location

<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action	L	Date:	

Overall Good: ☐

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type			
Comment:	Refer to Field Inspection Report doc. #696104494 and/or Location ID #305433 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	<input style="width: 500px;" type="text"/>
Corrective Action:	<input style="width: 500px;" type="text"/> Date: _____

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type			
Comment:	Refer to Field Inspection Report doc. #696104494 and/or Location ID #305433 for Battery / Facility, Equipment info.		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	Appears plumbed to surface.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type:	#		
Comment:	Refer to Field Inspection Report doc. #696104494 and/or Location ID #305433 for Battery / Facility, Equipment info.		

Corrective Action:		Date:	
--------------------	--	-------	--

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.522142,-104.540648
<p>Comment: Centralized Battery serves 3 Location IDs (305433, 305536, 332454). (Well(s): 1: Shut-In   SI ; 2: Producing   PR).</p> <p>Refer to Field Inspection Report doc. #696104494 and/or Location ID #305433 for Battery / Facility, Equipment info.</p> <p>(Battery: West side) GPS Coordinates: 40.522190 / -104.540860 (Battery: East side) GPS Coordinates: 40.522142 / -104.540648</p>					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 278877 Type: WELL API Number: 123-23107 Status: PR Insp. Status: PR**Producing Well**Comment: Producing | PR.

Corrective Action:

Date:

**BradenHead**Date of Last Brhd Test: 11/08/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On TUE 04/13/2021 at approximately 17:20 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: PDC ENERGY INC  Location Name: RUFF-66N64W /3SEW  Location ID: 305536  Well Name: Ruff 22-3  API: 05-123-23107  Location County: Weld County, Colorado  Weather: Mostly Cloudy, Dry.</p> <p>While there, I observed:  Well(s): 1: Producing   PR.  Battery (West side): Inactive   Shut-down.  Battery (East side): Active.</p> <p>Centralized Battery serves 3 Location IDs (305433, 305536, 332454).  (Well(s): 1: Shut-In   SI ; 2: Producing   PR).</p> <p>Refer to Field Inspection Report doc. #696104494 and/or Location ID #305433 for Battery / Facility, Equipment info.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/21/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696104499	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408836">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5408836</a>