





COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 2. Well.

Ant Hill Unit 18-43

API: 05-103-10296

Inspection: 701500398



40.13681, -108.20527, 6074.5ft, 52°
04/20/2021 12:51:33 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Well gas leak.

Ant Hill Unit 18-43

API: 05-103-10296

Inspection: 701500398



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Separator & meter building.

Ant Hill Unit 18-43

API: 05-103-10296

Inspection: 701500398





40.13651, -108.20526, 6082.2ft, 1°
04/20/2021 12:53:04 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 6. Gas leak at tank.

Ant Hill Unit 18-43

API: 05-103-10296

Inspection: 701500398



40.13679, -108.20528, 6077.0ft, 278°

04/20/2021 12:51:43 PM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Chemical label.

Ant Hill Unit 18-43

API: 05-103-10296

Inspection: 701500398



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 8. Sediment flow coming off location.

Ant Hill Unit 18-43

API: 05-103-10296

Inspection: 701500398

31 OPERATING

A.H.U. #18-43

SW SE SEC.18-T2N-R96W

RIO BLANCO COUNTY, CO

#C-0127535

IN CASE OF EMERGENCY CALL

EMERGENCY NUMBER : 800-209-9762

COUNTY ROAD 71

Lat: 40.13677 Long: 108.20527 40.13664, -108.2049, 6077.9ft, 12°
04/20/2021 12:50:02 PM