

Huber Lewis 2 #33

Corrective Actions Taken on the Huber Lewis 2 #33 for COGCC
Compliance INC.

Huber Rhoads 2 #33

04/19/21



Storm Water management controls have been established along eastern edge of the location to stabilize erosion. Installed a diversion that runs north to south on the eastern edge of location that will spill the storm water out on the contour in a flat area north of the north rig anchor. Treated the barren areas that had vegetation die-off with Humate soil conditioner and re-seeded.

