

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/21/2021

Submitted Date:

04/21/2021

Document Number:

701101396

**FIELD INSPECTION FORM**Loc ID 335619 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

10 Number of Comments

3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Inspection, Terra TEP	970-285-9377	COGCCInspectionReports@terraep.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280767	WELL	PR	10/20/2005	GW	045-11352	CHEVRON NG 323-8	PR
280768	WELL	PR	10/20/2005	GW	045-11353	CHEVRON NG 14-8	PR
280769	WELL	PR	10/20/2005	GW	045-11354	CHEVRON NG 24-8	PR
280770	WELL	PR	04/09/2009	GW	045-11355	CHEVRON NG 13-8	PR

**General Comment:****COGCC Follow Up Inspection Report Summary**

Location is in close proximity of Parachute creek and in a High Priority Habitat Area. (Black Bear, Mule Deer Winter Concentration Area, Elk Winter Concentration Area)

Follow up to 03/01/2021 inspection doc # 701101212

Uncomplete corrective action item:

1) Low water drains across access road need maintained. Ditch on access road needs maintained. Culvert and ditch into culvert on main road need maintained.

During this inspection the following compliance issues were observed:

1) Fencing material and derelict fence around north east reclaim area of location near the creek. 2" tubing laying off side location across from separators and tank battery.

2) Battery sign not at battery.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

**Location**Overall Good: ☐

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Battery sign not at battery.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	07/25/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Fencing material and derelict fence around north east reclaim area of location near the creek. 2" tubing laying off side location across from separators and tank battery.		
Corrective Action:	Comply with Rule 606	Date:	05/06/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 4	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 4	
Comment:	Braden head accessible for monitoring.	
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	210 bbl	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	280767	Type:	WELL	API Number:	045-11352	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	280768	Type:	WELL	API Number:	045-11353	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	280769	Type:	WELL	API Number:	045-11354	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	280770	Type:	WELL	API Number:	045-11355	Status:	PR	Insp. Status:	PR
<b>Producing Well</b>									
Comment:	Producing well								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Drains				
Seeding						
Gravel						
Compaction						
		Compaction				
		Culverts				
Ditches						
		Ditches				
		Gravel				

Comment: [Low water drains across access road need maintained. Ditch on access road needs maintained. Culvert and ditch into culvert on main road need maintained.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 03/15/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101397	Inspection 701101396 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5410017">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5410017</a>