

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|-------------------|-------|--|
| | Type WELLHEAD | | |
| | Comment: Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

| | | | |
|--------------------|--|-------|--|
| Comment: | <input style="width: 95%;" type="text"/> | | |
| Corrective Action: | <input style="width: 95%;" type="text"/> | Date: | <input style="width: 80%;" type="text"/> |

Overall Good:

Spills:

| Type | Area | Volume | | | |
|------|------|--------|--|--|--|
| | | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

| | | | |
|--------------------|-----------------|-------|--|
| | Type WELLHEAD | | |
| | Comment: Panels | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | | | |
|--------------------|--|-------|--|--|-----------------|
| | | | | | corrective date |
| Type: Plunger Lift | # 1 | | | | |
| Comment: | <input style="width: 95%;" type="text"/> | | | | |
| Corrective Action: | | Date: | | | |
| Type: Bradenhead | # 1 | | | | |
| Comment: | Appears to be plumbed to surface. | | | | |
| Corrective Action: | | Date: | | | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | NO | | |
| Comment: | <input style="width: 95%;" type="text"/> | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | <input style="width: 95%;" type="text"/> | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 298347 Type: WELL API Number: 123-29039 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary On (4/21/21) at approximately, I, Inspector (Abe Serna), Conducted an on-site inspection at (Schmier B 32-32) (Noble Energy), at (API # 123-29039) in (Weld County) Colorado. While there, I observed a (TA Well) During this inspection no compliance issues were observed. No follow up on this site inspection needs to be conducted. This is a summary of inspection report.</p> | sernaa | 04/21/2021 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---|
| 698702991 | Photo | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5410022 |