

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/22/2021

Submitted Date:

04/22/2021

Document Number:

688500309

**FIELD INSPECTION FORM**

Loc ID \_\_\_\_\_ Inspector Name: CANFIELD, CHRIS On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 46290  
Name of Operator: KP KAUFFMAN COMPANY INC  
Address: 1675 BROADWAY, STE 2800  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 4 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
Inspections, KPK		cogcc@kpk.com	<a href="#">All KPK Inspections</a>
Max Knop		mknop@kpk.com	

**General Comment:**

[This is an environmental inspection of REM 16131. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contractor personnel on location at the time of this inspection.](#)

**Environmental**

**Spills/Releases:**

Type of Spill: OIL Estimated Spill Volume: \_\_\_\_\_

Comment: There is an open, partially flooded excavation which the operator has surrounded with steel barricade panels.No activity at the time of this inspection.

Corrective Action: Provide notice to COGCC at least 48-hours in advance to backfilling any open excavations related to REM 16131. Date: 04/12/2021

Reportable: \_\_\_\_\_ GPS: Lat \_\_\_\_\_ Long \_\_\_\_\_

Proximity to Surface Water: \_\_\_\_\_ Depth to Ground Water: \_\_\_\_\_

**Water Well Complaint:**

DWR Receipt Num: \_\_\_\_\_ Owner Name: \_\_\_\_\_ GPS : \_\_\_\_\_ Lat \_\_\_\_\_ Long \_\_\_\_\_

**Field Parameters:**

Sample Location: \_\_\_\_\_ Comment: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
This is an environmental inspection of REM 16131. Any corrective actions from previous inspections that have not been addressed are still applicable. There were no operator or contractor personnel on location at the time of this inspection.	canfield	04/22/2021