

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/22/2021

Submitted Date:

04/25/2021

Document Number:

696104514

FIELD INSPECTION FORMLoc ID 305790 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@nblenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282360	WELL	PA	11/07/2018	OW	123-23483	ORR 44-3	PA

General Comment:

This is a **PLUGGED & ABANDONED WELL** inspection.
 Well(s): 1: Plugged & Abandoned | PA.
 Battery: Inactive. Shut-down.

Centralized Battery serves 1 Location ID
 (305789).
 (Well(s): 4: Shut-In | SI).

Centralized Battery formerly served 1 Location ID
 (305790).
 (Well(s): 1: Plugged & Abandoned | PA).

Refer to Field Inspection Report doc. #696104512 and/or Location ID #305789
 for Battery / Facility, Equipment info.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Gas Meter Run

0

Comment: [Plugged & Abandoned | PA.](#)
[Equipment now assigned to Location ID #305789.](#)Corrective Action: Date:

Type: Plunger Lift

0

Comment: [Plugged & Abandoned | PA.](#) Equipment removed.Corrective Action: Date:

Type: Emission Control Device

0

Comment: [Plugged & Abandoned | PA.](#)
[Equipment now assigned to Location ID #305789.](#)Corrective Action: Date:

Type: Horizontal Heated Separator

0

Comment: [Plugged & Abandoned | PA.](#)
[Equipment now assigned to Location ID #305789.](#)Corrective Action: Date: **Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment: Plugged & Abandoned PA. Equipment now assigned to Location ID #305789.						
Corrective Action: <input type="text"/>						Date: <input type="text"/>

PaintCondition: Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment: <input type="text"/>				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment: Plugged & Abandoned PA. Equipment now assigned to Location ID #305789.						
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 282360 Type: WELL API Number: 123-23483 Status: PA Insp. Status: PA

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On THU 04/22/2021 at approximately 15:22 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Location Name: ORR-66N64W /3SESE Location ID: 305790 Well Name: Orr 44-3 API: 05-123-23483 Location County: Weld County, Colorado Weather: Mostly Cloudy, Dry.</p> <p>While there, I observed: Well(s): 1: Plugged & Abandoned PA. Battery: Inactive. Shut-down.</p> <p>Centralized Battery serves 1 Location ID (305789). (Well(s): 4: Shut-In SI).</p> <p>Centralized Battery formerly served 1 Location ID (305790). (Well(s): 1: Plugged & Abandoned PA).</p> <p>Refer to Field Inspection Report doc. #696104512 and/or Location ID #305789 for Battery / Facility, Equipment info.</p> <p>WELL STATUS COMMENT: Plugged & Abandoned PA. Well appears to be cut / capped. Form 6 doc. #401692313 indicates plugging, cut/cap date: 11/07/2018. Approved.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	04/25/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402669840	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5412095