

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

04/13/2021

Submitted Date:

04/25/2021

Document Number:

688310376

**FIELD INSPECTION FORM**
 Loc ID 435414 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10706

Name of Operator: D90 ENERGY LLC

Address: 202 TRAVIS STREET #402

City: HOUSTON State: TX Zip: 77002

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
James, Cole	719-892-0378	cj0378@hotmail.com	Pumper
Oakes, Kevin	713-227-0391	kevin@d90energy.com	Designated Agent
Craig, Bill	719-650-4991	jwcranch@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
435415	WELL	SI	06/01/2018	OW	073-06568	JOHN CRAIG 4-2	TA

**General Comment:**

Reinspection, MIT-document #402645869 21 -00 Test Date: 12/10/2019 Final Case Pressure: 360 Pressure Loss or Gain: -2 Bridge Plug Depth: /Top Packer Depth: 7044 IN PROCESS

See document #402492194 WARN -00 Letter IN PROCESS for Form 7s requirement, 10/2020 last reported production to database

Document #402190896 10 (CO)(CC) Type: Change of Operator IN PROCESS 3/25/2020

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	D90 signs-Form 10 is in process		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	LOCATION		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:					
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance



**Inspected Facilities**Facility ID: 435415 Type: WELL API Number: 073-06568 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Form 7s to 10/2020, not up to date, See document #402492194 WARN -00 Letter IN PROCESSCorrective Action: Operator shall submit any delinquent forms, notices, or reports; and correct any incomplete or inaccurate reports. Confirm that all required Form 7s are submitted, accurate, and up-to-date.Date: 01/15/2021

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
Gravel	Pass	Gravel	Pass			
Other	Pass					other-vegetation

Comment: [fenced in pasture](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688310414	D90 Energy John Craig 4-2	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413539">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413539</a>