

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/27/2021

Submitted Date:

04/27/2021

Document Number:

679603836

FIELD INSPECTION FORMLoc ID 455319 Inspector Name: Santistevan, Brittani On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10177

Name of Operator: ENERPLUS RESOURCES (USA) CORPORATION

Address: 950 17TH STREET #2200

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

13 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		jeverhart@enerplus.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455318	WELL	XX	06/11/2020		123-46985	Lethbridge 8-67-20-19C	ND
455320	WELL	PR	09/23/2019	OW	123-46986	Edmonton 8-67-20-19N	PR
455321	WELL	XX	06/11/2020		123-46987	Airdrie 8-67-20-19C	ND
455322	WELL	XX	06/11/2020		123-46988	Medicine Hat 8-67-20-19C	ND
455323	WELL	XX	06/11/2020		123-46989	Red Deer 8-67-21-22C	ND
455324	WELL	PR	04/06/2021	OW	123-46990	St. Albert 8-67-21-22C	PR
455325	WELL	XX	06/11/2020		123-46991	Calgary 8-67-21-22C	ND
455326	WELL	XX	06/11/2020		123-46992	GRAND PRARIE 8-67-21-22N	ND

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	2 tanks do not have labeling. See attached photos.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	12/28/2020
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type			
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Compressor	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flare	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		

Comment:		Date:	
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:		Date:	
Corrective Action:		Date:	
Type: Bradenhead	# 2		
Comment:		Date:	
Corrective Action:		Date:	
Type: Plunger Lift	# 2		
Comment:		Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	2	OTHER	FIBERGLASS AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	UNKNOWN
Other (Capacity)	UNKNOWN
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares containment with crude oil tanks.			
Corrective Action:	Date:			

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	6	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:	Date:				

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:	Date:			

Inspected Facilities

Facility ID: 455318 Type: WELL API Number: 123-46985 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED.
Refer to previous inspection DOC#: 679603435 or well file for form 2.

Corrective Action: Date:

Facility ID: 455320 Type: WELL API Number: 123-46986 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date:

Facility ID: 455321 Type: WELL API Number: 123-46987 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED.
Refer to previous inspection DOC#: 679603435 or well file for form 2.

Corrective Action: Date:

Facility ID: 455322 Type: WELL API Number: 123-46988 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED.
Refer to previous inspection DOC#: 679603435 or well file for form 2.

Corrective Action: Date:

Facility ID: 455323 Type: WELL API Number: 123-46989 Status: XX Insp. Status: ND

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: SITE CONDITION

Comment: NOT DRILLED.
Refer to previous inspection DOC#: 679603435 or well file for form 2.

Corrective Action: Date:

Facility ID: 455324 Type: WELL API Number: 123-46990 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date:

Facility ID: 455325 Type: WELL API Number: 123-46991 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: NOT DRILLED.

Refer to previous inspection DOC#: 679603435 or well file for form 2.

Corrective Action:

Date:

Facility ID: 455326

Type: WELL

API Number: 123-46992

Status: XX

Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: SITE CONDITION

Comment: NOT DRILLED.

Refer to previous inspection DOC#: 679603435 or well file for form 2.

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>THIS IS A FOLLW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679603435. All previous corrective actions that have been assigned to this location have not been resolved. They will be re-assigned to this location with their original corrective action date. No new corrective actions were observed at the time of re-inspection.</p> <p>COGCC Inspection Report Summary **Weather Conditions: cloudy, dry ground On Tuesday, April 27, 2021 at approximately 9:30, I, Inspector Brittani Santistevan, conducted an on-site inspection at ALBERTA CITIES EAST PAD (Enerplus Resources), at location #: 455319 in WELD COUNTY Colorado. While there, I observed a producing facility. During this inspection the following possible compliance issues were observed: 1. Two tanks do not contain any labeling (contents, volume, NFPA placard). Install sign to comply with Rule 605.h. (Corrective Action Date: December 28, 2020) See attached photos #2, 3.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	santistb	04/27/2021

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679603837	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5413949