



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

| Type | Area | Volume |  |  |  |
|------|------|--------|--|--|--|
|      |      |        |  |  |  |

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PUMP JACK

Comment: Some stained soil that may need to be addressed soon by wellhead.

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Bradenhead # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Pump Jack # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Prime Mover # 1

Comment: gas motor

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Flaring:**

Type

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Inspected Facilities**

Facility ID: 244774 Type: WELL API Number: 123-12569 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: 07/29/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

**COGCC Comments**

| Comment   | User    | Date       |
|---|---------|------------|
| At time of inspection location appears to be in compliance with COGCC rules.<br>At time of inspection weather conditions were cloudy, warm, calm. | medinaj | 04/26/2021 |

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL   |
|--------------|-------------|---|
| 699502680    | pics        | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414345">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414345</a> |