

Inspection Photos
Operator: Catamount Energy
API: 007-06207
Date: 4/20/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is in an early reclamation condition. Small grasses such as squirreltail and western wheatgrass, as well as clover (likely melilotus) observed within the reclamation areas.



Photo 3. View of the northern project area facing westward. .



Photo 4. View of reference area vegetation comprised of Ponderosa pine savanna with western wheatgrass, squirreltail, black sagebrush, locoweed, brittle prickly pear, and bisquitroot.