

Inspection Photos

Operator: Catamount Energy
API: 007-06137
Date: 4/20/2021



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Vegetation remains in-tact here, with grasses such as western wheatgrass.



Photo 3. View of the eastern project area facing southward. Revegetation is in an early reclamation condition. Small grasses such as squirreltail and western wheatgrass, as well as clover (likely melilotus) observed within the reclamation areas.



Photo 4. View of reference area vegetation comprised of Ponderosa pine and gambel oak woodland with understory of sagebrush and western wheatgrass.