

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 1 WH sign**

**Photo 2 WH**

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 3 Pump Jack**

**Photo 4 ancillary equipment**

Inspection Photos  
Location Name: Alfred Herman #1  
Location ID: 332917



Photo 5 TB sign

Photo 6 TB

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 7 Horizontal Heated Separator**

**Photo 8 Stained soil under Horiz. Heated Sep**

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 9 Flow line manifold**

**Photo 10 Stained soil around flow line manifold**

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 11 sink hole south of separator house**

**Photo 12 sink hole south of separator house**

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 13 Stained soil inside Horiz. Sep. house**

**Photo 14 Stained soil inside Horiz. Sep. house**

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 15 Stained soil inside Horiz. Sep. house**

**Photo 16 Stained soil by crude oil tank valve**

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 17 Stained soil between crude oil tanks**

**Photo 18 Stained soil by crude oil tank valve**

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 19 Gas Meter Run no card indicating calibration status**

**Photo 20 Gas Meter Run no card indicating calibration status**

**Inspection Photos**  
**Location Name: Alfred Herman #1**  
**Location ID: 332917**



**Photo 21 Tank volume & placards faded.**