

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2021

Submitted Date:

04/27/2021

Document Number:

699303772

FIELD INSPECTION FORM

Loc ID 317922 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

15 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections
,		rwatzman@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240187	WELL	PR	02/01/2020	OW	123-07975	BANGERT 42-19	PR
453314	TANK BATTERY	AC	12/06/2017		-	Bangert 41-19 & 42-19 battery	AC

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil by WH and in PJ base		
Corrective Action:	Comply with Rule 1002..(2).D	Date:	07/27/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	TANK BATTERY		
Comment:	barb wire		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Well site has barb wire fencing around well site is in disrepair.		
Corrective Action:	Comply with rule 1002..(2).D Self-inspection, maintenance, and good housekeeping procedures.	Date:	07/27/2021

Equipment:

			corrective date
Type: Bradenhead	# 1		
Comment:	appears to be plumbed to surface		
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	automation, electric panel, meter box and transformers		
Corrective Action:		Date:	

Type: Prime Mover	# 1		
Comment:	electric motor		
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	no card in meter box to indicate calibration status.		
Corrective Action:	Provide calibration records or calibrate meter as required by Rule 429 & 430. Proof of calibration may be provided on a Field Inspection Resolution Report (FIRR).		Date: 07/27/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	80 bbl
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:	shares containment with crude tank		
Corrective Action:		Date:	

Wells Served By Facilities Above**AirsID**

API Number

API Number

AirsID

123-07975

123-09150

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240187 Type: WELL API Number: 123-07975 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 11/03/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 453314 Type: TANK API Number: - Status: AC Insp. Status: AC

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
On Tuesday 4/27/2021 at approximately 1345 hrs. I, Inspector Robbie Revas,
Conducted an on-site inspection at a KP Kauffman location:

Bangert 42-19 at API #05-123-
07975 in Weld County Colorado.

While there, I observed a wellsite and tank battery, PR at time of inspection.
During this inspection the following possible compliance issues were observed:
Rule 429/430 Measurement of Oil & Gas: No card in meter box to indicate calibration status,
CA date 7-27-2021.
Rule 1002..(2).D house keeping: Stained soil by the WH and fencing in disrepair around
well site, CA date 7-27-2021.
See attached photos.
Location: wet/muddy, Weather: cloudy/overcast raining.
A follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

revasr

04/27/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699303773	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414472