

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/27/2021

Submitted Date:

04/27/2021

Document Number:

693803033

FIELD INSPECTION FORM

Loc ID 314881 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100264
Name of Operator: XTO ENERGY INC
Address: 110 W 7TH STREET
City: FORT WORTH State: TX Zip: 76102

Findings:

- 7 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|--------------------------------|---------------------------------|
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |
| Clark, Erin | 405-319-3250 | Erin_clark@xtoenergy.comgy.com | XTO Piceance and BOPCO Piceance |
| Morgan, John | | john.morgan@state.co.us | |
| Labowskie, Steve | | steve.labowskie@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------------|-------------|
| 229821 | WELL | TA | 01/17/2020 | DSPW | 103-07478 | U S A-PICEANCE CREEK F13-1G | TA |

General Comment:

UIC-5 yr MIT. Wellhead inspection only.

| Location | | | |
|--|---------------------------|--------|-----------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective ActionL | | Date: | |
| Type | Main | | |
| comment: | | | |
| Corrective ActionL | | Date: | |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign at location entrance | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | 970-675-4117 or 911 | | |
| Corrective Action: | | Date: | _____ |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | _____ | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | WELLHEAD | | |
| Comment: | Panel fence | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Bradenhead | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Venting: | | | |
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |

| | |
|--------------------|-------|
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 229821 Type: WELL API Number: 103-07478 Status: TA Insp. Status: TA

Underground Injection Control

UIC Violation: _____ Maximum Injection Pressure: _____

UIC Routine

| | | | |
|------------|---|------------------------------|-----------------------------|
| Inj./Tube: | Pressure or inches of Hg _____ (e.g. 30 psig or -30" Hg) | Previous Test Pressure _____ | MPP _____ |
| TC: | Pressure or inches of Hg _____ | Previous Test Pressure _____ | Inj Zone: <u>WSTCA</u> |
| Brhd: | Pressure or inches of Hg _____ | Previous Test Pressure _____ | Last MIT: <u>04/28/2016</u> |
| | | | AnnMTReq: _____ |

Comment: _____

Corrective Action: _____ Date: _____

Method of Injection: _____

Test Type: 5 Year Tbg psi: 150 Csg psi: 610 BH psi: 0

Insp. Status: Pass

Comment: UIC-5 yr MIT. Wellhead inspection only.
Form 42 Doc#402657943 received 4/14/2021, with test scheduled for 4/27/2021.
Pressure well to 610 psi. Hold for 15 min. Final pressure 608 psi. -2psi loss. OK
Test witnessed by COGCC using chart on wellhead.

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------------------|---|
| 693803034 | Inspection photos 4/27/2021 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5414628 |