

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/20/2021

Submitted Date:

04/21/2021

Document Number:

701500398

FIELD INSPECTION FORM

 Loc ID: 316341
 Inspector Name: Moran, Rick
 On-Site Inspection:
 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 200502
 Name of Operator: 31 OPERATING
 Address: 3021 RIDGE RD #156
 City: ROCKWALL State: TX Zip: 75032
Findings:

- 12 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Boulger, Levin		lboulger@31operating.com	
Thompson, Bud		BLThomps@BLM.gov	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
267099	WELL	SI	10/01/2020	GW	103-10296	ANT HILL UNIT 18-43	SI

General Comment:

A follow up inspection of documents:
1) FIR 701500342 dated 4-14-2021.

The following compliance issues are uncompleted:

- 1) Fitting leaks at well & tank. Photos 3 & 6 . Complete by 4-16-2021.
- 2) Chemical label illegible. Photo 7. Complete by 6-15-2021.
- 3) No battery sign present. Photos 5 & 9. Complete by 6-15-2021.
- 4) Stormwater sediment flow off edge of location. Photo 8. Complete by 6-15-2021.
- 5) Production history not current.

Note: The emergency phone 800-209-9762 was called on 4-20-2021 @ 16:33 to report the leak. Phone call was returned @ 17:54.

Location is within a Rule 1202.d Mule deer severe winter range area, and Rule 1202.d Mule deer winter concentration area.

This is a summary of inspection report 701500398.

Location

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:	Chemical label is illegible.		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	06/15/2021
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign present.		
Corrective Action:	Install sign to comply with Rule 605.e.	Date:	06/15/2021
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	800-209-9762		
Corrective Action:		Date:	_____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:			corrective date
Type: Gas Meter Run	# 1		
Comment:	Telemetry.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead access pesent.		

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical container.		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Fluid & gas leak present at well. Gas leak present at tank pipe fitting.		
Corrective Action:	Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 04/16/2021

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	
Comment:	

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 267099 Type: WELL API Number: 103-10296 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Last reported monthly operations were January 2021. Production is missing for July 2020 to September 2020. Most recent reported production June 2020. Report past due monthly operations.

Submit required Form 7(s) to COGCC per rule 413.a.

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				
				Material Handling And Spill Prevention		Chemical secondary containment.
Retention Ponds		Culverts				
Other						Cattle guard.

Comment: Stormwater sediment flow coming off location.

Corrective Action: Install, maintain, or provide documentation of post construction management plan or BMP's.

Date: 06/15/2021

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402666774	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5409553
701500399	inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5409544