

TEP
KP 32-9
Location # 435118



location



location



TEP
KP 32-9
Location # 435118



Location/ No battery signage



location



TEP
KP 32-9
Location # 435118



Lack of stabilization/compaction on access road



TEP
KP 32-9
Location # 435118




Cut slope on access road lacks stabilization



Cut slope on access road lacks stabilization. This photo is above culvert in next photos.



TEP
KP 32-9
Location # 435118



Inlet side of culvert on access road and lack of stabilization/compaction. Culvert is depicted by arrow



Inlet side of culvert on access road. Culvert is depicted by arrow

TEP
KP 32-9
Location # 435118



Inlet side of culvert on access road and lack of stabilization/compaction. Culvert is depicted by arrow



Inlet side of culvert on access road and lack of stabilization/compaction. Culvert is depicted by arrow



TEP
KP 32-9
Location # 435118



Lack of stabilization/compaction



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

TEP
KP 32-9
Location # 435118



Inlet side of culvert on location



Outlet side of culvert on location



TEP
KP 32-9
Location # 435118



Sediment trap on outlet side of culvert on location



Debris



TEP
KP 32-9
Location # 435118



Debris



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources