

TEP
KP 24-23
Location # 324439



location



location



TEP
KP 24-23
Location # 324439



location



Lack of stabilization/compaction



TEP
KP 24-23
Location # 324439



Lack of stabilization/compaction



Debris



TEP
KP 24-23
Location # 324439



Debris

TEP
KP 24-23
Location # 324439



Debris

TEP
KP 24-23
Location # 324439



Staining

TEP
KP 24-23
Location # 324439



Staining and secondary containment failing

